

EASA APPROVAL EASA.21J.722

CABIN INTERIOR REPAIRS



aes
aerospace engineering solutions

FAST, RELIABLE & EASA CERTIFIED CABIN INTERIOR REPAIRS

At AES, we specialise in providing fast, reliable, and EASA-certified interior cabin repair solutions for all types of aircraft. Whether you're dealing with AOG situations or routine maintenance, our team delivers permanent repairs with no additional inspections required, ensuring a seamless experience every time.

From galley and lavatory refurbishments to seats, ducting, piping, and beyond, we're equipped to handle metallic and non-metallic interior structures with precision and care. With our on-site support and capability to manufacture approved repair parts, we guarantee quick turnaround times and a commitment to quality that ensures your fleet remains operational smoothly.

NEED CABIN REPAIRS? WE'VE GOT YOU COVERED

Our key capabilities include:

- EASA certified repair solutions
- Permanent repairs with no additional inspections
- On-site support (if required) for seamless operations
- Manufacture of approved repair parts
- Expertise in metallic and non-metallic interior structures

We work across all major components:

- Lavatories
- Galleys
- Interior furnishings
- Seats
- Overhead storage compartments (OHSC)
- Ducting and piping

REPAIR TO PASSENGER CABIN GALLEYS & MONUMENTS

Case study: Repair to G4b galley (Safran Spaceflex)



Reported damage / Issue



- Movement detected in galley shelf panel
- No CMM repair scheme available
- OEM unable to support return-to-service timeline
- Aircraft grounded due to unserviceable galley

AES Solution

- Developed bespoke permanent repair scheme to eliminate shelf movement
- Manufactured custom repair parts to support the solution

REPAIR TO PASSENGER CABIN GALLEYS & MONUMENTS

Case study: Repair to G1 galley



Reported damage / Issue

- Underside of composite galley workdeck damaged
- Metallic internal structure also affected
- No CMM repair scheme available
- OEM unable to support return-to-service timeframe
- Aircraft grounded due to unserviceable galley

AES Solution

- Developed a bespoke permanent repair scheme
- Repair included both composite and metallic components
- On-site support provided to expedite the process

REPAIR TO PASSENGER CABIN GALLEYS & MONUMENTS

Case study: Repair to aft cabin lavatory



Reported damage / Issue



- Corrosion at lavatory lower fittings
- Delamination and cracks in panel skins
- No CMM repair scheme available
- OEM unable to meet return-to-service timeline
- Aircraft grounded due to unserviceable lavatory

AES Solution

- Developed bespoke permanent repair scheme
- Repaired composite skin and core
- Added repair doublers to restore strength
- Sourced and reinstalled replacement fittings

REPAIR TO PASSENGER CABIN GALLEYS & MONUMENTS

Case study: Repair to G1 galley (Driessen)



Reported damage / Issue


- Damage to underside of composite galley workdeck
- Damage to metallic internal structure of galley workdeck
- No CMM repair scheme available
- OEM unable to meet return-to-service timeline
- Aircraft grounded due to unserviceable galley

AES Solution

- Developed bespoke permanent repair scheme
- Repaired composite and metallic components
- Provided on-site support to expedite the repair

REPAIR TO PASSENGER CABIN GALLEYS & MONUMENTS

Case study: Repair to G4 galley (Driessen)



Reported damage / Issue

- Damage to underside of composite galley workdeck
- Damage to metallic internal structure of galley workdeck
- No CMM repair scheme available
- OEM unable to meet return-to-service timeline
- Aircraft grounded due to unserviceable galley

AES Solution

- Developed bespoke permanent repair scheme
- Repaired composite and metallic components
- Provided on-site support to expedite the repair

REPAIR TO PASSENGER CABIN GALLEYS & MONUMENTS

Case study: Repair to galley cart stops



Reported damage / Issue


- Damage at galley cart stops
- Honeycomb panel damage
- No CMM repair scheme available
- OEM unable to meet return-to-service timeline
- Aircraft grounded due to unserviceable galley

AES Solution

- Developed bespoke permanent repair scheme
- Repaired composite skin/core and re-potted inserts
- Added repair doublers to restore strength and prevent future damage

REPAIR TO PASSENGER CABIN FURNISHINGS

Case study: Repair to A320 Family cabin ceiling panels



Reported damage / Issue

- Cracks in composite panel at production joint line
- Debonding along joint line
- No AMM/SRM repair scheme available
- OEM unable to meet return-to-service timeline
- Aircraft grounded due to unserviceable panels


AES Solution

- Developed bespoke permanent repair scheme
- Re-bonded production joint line
- Added composite repair doublers to restore strength



REPAIR TO PASSENGER CABIN FURNISHINGS

Case study: Repair to Boeing 737 lavatory



Reported damage / Issue

- Damage to composite panel near lower lavatory fittings
- Corrosion on lower fittings
- OEM unable to meet return-to-service timeline

AES Solution

- Developed bespoke permanent repair scheme
- Applied existing CMM repair with custom AES-manufactured parts to reduce lead time

REPAIR TO PASSENGER CABIN FURNISHINGS

Case study: Repair to A320 Family cove light panel



Reported damage / Issue

- Cracking in composite panel at production joint line.
- Debonding along joint line
- No AMM/SRM repair scheme available
- OEM unable to meet return-to-service timeline
- Aircraft grounded due to unserviceable panels

AES Solution

- Developed bespoke permanent repair scheme
- Re-bonded production joint line
- Introduced composite repair doublers to restore strength

REPAIR TO PASSENGER CABIN FURNISHINGS

Case study: Repair to A320 Overhead Stowage Compartment



Reported damage / Issue

- Multiple composite panel damages at attachment points
- Composite skin and core damage
- No AMM/SRM repair scheme available
- OEM unable to meet return-to-service timeline
- Aircraft grounded due to unserviceable OHSC

AES Solution

- Developed bespoke permanent repair scheme
- Added metallic repair doublers and composite patches to restore panel strength

REPAIR TO PASSENGER CABIN FURNISHINGS

Case study: Repair to Airbus A320 Spacer Bin



Reported damage / Issue



- Damage to spacer bin lower floor panel near inserts
- Composite skin and core damage
- Metallic insert damage
- No AMM/SRM repair scheme available
- OEM unable to meet return-to-service timeline
- Aircraft grounded due to unserviceable spacer bin

AES Solution

- Developed bespoke permanent repair scheme to restore panel strength and reintroduce attachment points

REPAIR TO PASSENGER CABIN SEATS

Case study: Repair to Cabin Attendant Seat (CAS)



Reported damage / Issue

- Cracked metallic diaphragm on CAS
- No CMM repair scheme available
- Aircraft grounded due to unserviceable CAS

AES Solution

- Developed bespoke permanent repair scheme to restore diaphragm strength

EASA APPROVAL EASA.21J.722

CERTIFY YOUR IDEAS, MAKE THEM FLY



aes
aerospace engineering solutions

GET IN TOUCH TO DISCUSS YOUR CABIN INTERIOR REPAIRS
INFO@AESGLOBAL.CO.UK